



亏.2






	TEMPERATURE (°C)	TIME (SECOND)	HEATING MODE
1	150	20	RUMP
2	250	10	RUMP
3	1000	10	RUMP
4	1000	10	STEP
5	2300	2	STEP
6	2500	2	STEP



FOJ. 5 (PRIOR ART)



F3-6 (PRIOR ART)